



Order No. Blower with old VFD	Order No. Successor	Nominal Power of installed FC [kW]	Remarks
2BH1300-7AN21	2BH1300-7A221	1.5	
2BH1330-7AN21	2BH1330-7A221	1.5	
2BH1310-7HN21	2BH1310-7H221	1.5	
2BH1400-7AN21	2BH1400-7A221	2.2	
2BH1430-7AN21	2BH1430-7A221	2.2	
2BH1410-7HN41	2BH1410-7H241	4	
2BH1500-7AN31	2BH1500-7A231	4	
2BH1530-7AN31	2BH1530-7A231	4	
2BH1510-7HN51	2BH1510-7H156	7.5	Only available in IE1 efficiency
2BH1600-7AN31 2BH1600-7AL36	2BH1600-7A231	7.5	
2BH1630-7AN31 2BH1630-7AL36	2BH1630-7A231	7.5	
2BH1610-7HN31	2BH1610-7H231	7.5	
2BH1800-7AN01	2BH1800-7A221	11	smaller performance on request
2BH7210-0AN11-7	2BH7210-0A211-7	1.5	
2BH7210-0AN51-7	2BH7210-0A256-7	2.2	
2BH7220-0AN51-7	2BH7220-0A251-7	3	
2BH7310-0AN21-7	2BH7310-0A241-7	2.2	Old motor not available as IE2 version
2BH7310-0AN51-7	2BH7310-0A251-7	3	
2BH7320-0AN51-7	vacuum: 2BH7320-0A251-7 compressor: 2BH7420-0A261-7	3	
2BH7320-0AN81-7		5.5	
2BH7410-0AN11-7	2BH7410-0A221-7	3	Old motor not available as IE2 version Nominal power of FC exceeded
2BH7410-0AN51-7	2BH7410-0A231-7	4	Old motor not available as IE2 version
2BH7420-0AN21-7	2BH7420-0A221-7	3	
2BH7420-0AN51-7	2BH7420-0A261-7	5.5	Old motor not available as IE2 version
2BH7420-0AL61-7			
2BH7510-0AN21-8	2BH7510-0A221-8	4	
2BH7520-0AN21-8	2BH7520-0A221-8	4	
2BH7520-0AN76-8	2BH7520-0A271-8	7.5	
2BH7610-0AN31-8	2BH7610-0A241-8	7.5	Old motor not available as IE2 version
2BH7610-0NN31-8	2BH7610-0N241-8	7.5	Old motor not available as IE2 version
2BH7620-0AN31-8	2BH7620-0A241-8	7.5	Old motor not available as IE2 version
2BH7620-0AN41-8			
2BH7620-0NN31-8	2BH7620-0N241-8	7.5	Old motor not available as IE2 version
2BH7620-0NN41-8			
2BH7630-0AN61-7	2BH7630-0A261-7	11	Nominal power of FC exceeded
2BH7630-0NN61-7	2BH7630-0N261-7	11	Nominal power of FC exceeded
2BH20360-1AANK6-AA	2BH20360-1AA2L1-AA	7.5	
2BH20360-1AANL6-AA			Nominal power of FC exceeded
2BH20360-1AANM6-AA	2BH20360-1AA2M1-AA	11	Nominal power of FC exceeded
2BH20360-2AANM6-AA	2BH20360-2AA2M1-AA	11	Nominal power of FC exceeded
2BH20540-1AANM6-AA	2BH20540-1AA2M1-AA	11	Nominal power of FC exceeded
2BH85100-1AANM0-AB	2BH85100-1AA1M0-AB	7.5	
2BH85200-1AANM0-AB	2BH85200-1AE1M0-AB	11	Nominal power of FC exceeded